This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

47601 JA-1996-420-109 AU 111 o 1 0 JAN 1976 JAPAN JA 0002615 GROUP__// JAN 1976 CLASS__ 19 日本国特許庁 RECORDEÓ 昭和49年6月25日 🚟 ①特開昭 51/2615 停許庁長官 (3)公開日 昭51. (1976) 1 10 2)特願昭 48-72621 -(22)出願日 昭49. (1974) 6.25 審査請求 未請求 (全4頁) 厅内整理番号 爱知泉又海市加木屋叮침池 1 1-5 1 9 7109 42 氏名 6547 42 **等许出**国人 2116 42 名古园市得区星時町字级出66各地 52日本分類 50 Int. C12 大同级简株式会社 = 1: 10. J172 C22C 35/481 万丈 [10 51 C28C 9/14 口弦 12 A32 C23C 11/16 权兵市段子区段子町 5 4 3 各地 及"川 ひねま 2 不然をこと 3.名選録のお取せ性を高め、 -042X/08 M27 DAIZ 25.06.74 117 M27-A4M. VIDO STEEL KK *J5 1002-615 25.06.74-JA-072621 (10.01.76) C22c-38/45 C23c-09/14 C23c-11/16 w alloy tool stool - suitable for soft nitriding, with age hardening A low alloy steel comprises 0.1-0.3% C. ≥1% Si, ≤2% /kn. ≤0-25% Ni, 0.3-2% Cr. 2-5% Mo, 0.05-0.5% Ti. 0.1-1% V. 0.05-1% Al. 0.05-0.5% Nb and remainder im-irities and iron. The steel is maintained at a temp. here age hardening and soft nitriding are achieved at the ıme ti ne.

を来の高色が皮(盤化)処理に代って、 及近低色でメフトライド(塩谷吹量化)処理、 ガス 吹理化処理、イオン盤化処理などが突用化され るにいたつた。 との私の低温盤化処理は高温が 皮盤化処理に比べて以処理とメミがきわめて少 餌材組成はつぎのとおりである。 すなわち、....

シ リュラン : 0 多以下.....

マンガン: 03-20.%

ニッケル: 0.25%以下

420/109/10